ANCHORAGE, ALASKA

TACAN Y RWY 16

TACAN	APCH CRS	Rwy Idg	7493
EDF Chan 81	133°	TDZE	213
		Arpt Elev	213

AL-1196 [USAF]

ELMENDORF AFB (PAED)

* Circling not authorized SW of Rwy 6 and 34.
CAT E aircraft remain within 4.5 NM of runway when executing circling maneuver.

MISSED APPROACH: Climbing left turn to 6000 via EDF R-313 to LUBEE and hold. Continue climb-in-hold to 6000.

ATIS *	ANCHORAGE APP CON	ELMENDORF TOWER	GND CON	CLNC DEL	PAR
124.3 273.5	118.6 290.5 North 123.8 259.3 South	127.2 352.05	121.8 275.8	128.8 306.925	

MISSED APPROACH NOT FOR CIVIL USE

Knots	60	120	180	240	300	360
V/V(fpm)	476	952	1428	1904	2380	2856

Min climb of 476 ft/NM to 3900 - Controlling Obstacle 2088

R-313
EDF 25
HOLD 8000 6000
133° 313°
(IAF) LUBEE
EDF 17
6000
3900
133°
CEGEN
EDF 12
960
2000
BETUN
EDF 6
R-2203B
R-2203C
R-2203A
2088
2988
263
456
375
555
ELMENDORF
Chan 81 EDF
MERRILL FLD

-CAUTION:
Terrain rises rapidly to the S and E.
-Winds in vicinity of higher terrain may produce severe turbulence.
-Uncontrolled light aircraft operations in the vicinity of Six-mile lake at or below 600.

MSA EDF 25 NM
153°
9000
2800
273°
003°
8500

EMERG SAFE ALT 100 NM 15,200

ANCHORAGE INTL

VGSI and descent angles not coincident (VGSI angle 3.00/TCH 47).

6000 | EDF R-313 | LUBEE

LUBEE R-313
17
6000
133°
3900
CEGEN
12
BETUN
6
2000
ALNOK
1.8
TACAN
3.08°
TCH 56
4.2 NM
1.2

ELEV 213 | TDZE 213
133° to TACAN
439
398
91
506
372
A1
227
0.4% DOWN
24
245
0.3% UP
10,000 x 200
TWR
335
7499 x 150
295
34
Drops off

CATEGORY	A	B	C	D	E
S-16	NOT AUTHORIZED				680-1⅜ 467 (500-1⅜)
C CIRCLING*	NOT AUTHORIZED				1420-3 1207 (1300-3)

HIRL all rwys
REIL Rwy 16
TDZL/CL Rwy 6

ANCHORAGE, ALASKA
Amdt 2 10SEP20

61°15'N-149°48'W

ELMENDORF AFB (PAED)

TACAN Y RWY 16

AK, 25 FEB 2021 to 22 APR 2021

AK, 25 FEB 2021 to 22 APR 2021