


LAKES THREE DEPARTURE

AL-6104 (FAA)

LEE'S SUMMIT MUNI (LXT)

LEE'S SUMMIT, MISSOURI

NC-3, 25 FEB 2021 to 25 MAR 2021



NOTE: Chart not to scale.

DEPARTURE ROUTE DESCRIPTION

TAKEOFF ALL RUNWAYS: Climb on assigned heading for RADAR vectors to appropriate route. Expect filed altitude 10 minutes after departure.

COLUMBIA TRANSITION (LAKES3.COU): From over MCI VORTAC on MCI R-107 to ANX VORTAC, then on ANX R-088 and COU R-292 to COU VOR/DME.

FRANC TRANSITION (LAKES3.FRANC): From over MCI VORTAC on MCI R-107 to ANX VORTAC, then on ANX R-088 to FRANC FIX.

SPINNER TRANSITION (LAKES3.SPI): From over MCI VORTAC on MCI R-075 and SPI R-265 to TWAIN FIX, then on SPI R-265 to SPI VORTAC.

TWAIN TRANSITION (LAKES3.TWAIN): From over MCI VORTAC on MCI R-075 and SPI R-265 to TWAIN FIX.



NOTE: RADAR required.
NOTE: DME required.

TAKEOFF MINIMUMS
Rwys 11, 18, 29, 36: Standard.

NC-3, 25 FEB 2021 to 25 MAR 2021