

LOC/DME I-FQS 110.55 Chan 42 (Y)	APP CRS 052°	Rwy Idg THRE 742 Apt Elev 744	11004
---	------------------------	---	--------------

ILS or LOC RWY 5L




COLUMBUS / RICKENBACKER INTL (LCK)

▲ Circling NA northwest of Rwy 5L-23R. When local altimeter setting not received, use Port Columbus Intl altimeter setting and increase all DA 36 Feet and all MDA 40 feet, increase S-LOC 5L visibility Cat C and D ½ mile; increase ZOGAM fix minimums visibility Cat C and D ⅓ mile.





MISSED APPROACH: Climb to 1500 then climbing right turn to 3000 direct XUB VOR and hold.

AWOS-3 132.75	COLUMBUS APP CON 119.15 279.6	RICK TOWER 120.05 348.4	GND CON 121.85 275.8
-------------------------	---	-----------------------------------	--------------------------------



ELEV 744	D THRE 742
----------	-------------------



CATEGORY	A	B	C	D
S-ILS 5L	942-½		200 (200-½)	
S-LOC 5L	1180-½	438 (500-½)	1180-¾	438 (500-¾)
CIRCLING	1180-1 436 (500-1)	1200-1 456 (500-1)	1200-1½ 456 (500-1½)	1300-2 556 (600-2)
ZOGAM FIX MINIMUMS				
S-LOC 5L	1080-½		338 (400-½)	
CIRCLING	1180-1 436 (500-1)	1200-1 456 (500-1)	1200-1½ 456 (500-1½)	1300-2 556 (600-2)

TDZ/CL Rwy 5R REIL Rwy 23R HIRL Rwy 5L-23R and 5R-23L					
FAF to MAP 5 NM					
Knots	60	90	120	150	180
Min:Sec	5:00	3:20	2:30	2:00	1:40

EC-2, 26 JUN 2014 to 24 JUL 2014

EC-2, 26 JUN 2014 to 24 JUL 2014