HOT SPOTS

An "airport surface hot spot" is a location on an aerodrome movement area with a history or potential risk of collision or runway incursion, and where heightened attention by pilots/drivers is necessary.

A "hot spot" is a runway safety related problem area on an airport that presents increased risk during surface operations. Typically it is a complex or confusing taxiway/taxiway or taxiway/runway intersection. The area of increased
risk has either a history of or potential for runway incursions or surface incidents, due to a variety of causes, such as
but not limited to: airport layout, traffic flow, airport marking, signage and lighting, situational awareness, and training.
Hot spots are depicted on airport diagrams as open circles or polygons designated as "HS 1", "HS 2", etc. and
tabulated in the list below with a brief description of each hot spot. Hot spots will remain charted on airport diagrams
until such time the increased risk has been reduced or eliminated.

ALISTIN TX			

HOT SPOT

ΑU	ST	IN,	TX
	ΑU	ST	IN-B

CITY/AIRPORT

AUSTIN-BERGSTROM

INTL (AUS) HS 1 E service road, Traffic on crossing Twy G and Twy H.

SAN MARCOS RGNL (HYI)

HS 1 Int of Rwy 26 and Rwy 35. HS 2 Int of Rwy 31, Twy F and Rwy 35.

EL PASO, TX

EL PASO INTL (ELP) HS 1

Rwy 08R apch considered active, do not proceed on or cross without ATC clnc especially when taxiing to Rwy 04 via the

DESCRIPTION*

terminal ramp.

HARLINGEN, TX

VALLEY INTL (HRL) HS 1 Rwy 31 and Rwy 35R apch ends are closely aligned.

MC ALLEN, TX

MC ALLEN MILLER INTL (MFE) HS 1 Rwy 14 hold short marking located in a non-standard location.

MIDLAND, TX

25 FEB 2021 to 25 MAR 202

MIDLAND INTL AIR AND SPACE HS 1 Twy B and Twy P merge.
PORT (MAF) HS 2 Area not visible from twr.

SAN ANGELO, TX

SAN ANGELO RGNL / MATHIS HS 1 Rwy 18-36 at the int of Rwy 09-27. FIELD (SJT) HS 2 Rwy 18-36 at the int of Twy D.

HS 3 Twy B close proximity to Rwy 18-36 and Rwy 03-21.

SAN ANTONIO, TX

LACKLAND AFB (KELLY FLD HS 1 The unpaved portion of the north overrun. ANNEX) (KSKF) HS 2 Int of Rwy 16-34, Twy D, and Twy G.

SAN ANTONIO INTL (SAT) HS 1 Rwy 31L hold short line on Rwy 04.

HS 2 Twy G and Twy N in close proximity of Rwy 31L.

^{*}See appropriate Chart Supplement HOT SPOT table for additional information.