

JONZE TWO ARRIVAL (RNAV)

ARRIVAL ROUTE DESCRIPTION

BESTT TRANSITION (BESTT.JONZE2)

CNTRLR TRANSITION (CNTRLR.JONZE2)

LANDING RWY 5: From JONZE on track 069° to cross DUBBB between 10000 and 12000, then on track 080° to cross CHELE at 7000 and at 210K, then on heading 020°. Expect RADAR vectors to final approach course.

LANDING RWYS 18L/C/R: From JONZE on track 054° to cross WHYLE between 10000 and 16000, then on track 054° to cross FREEK between 9000 and 11000 and at 250K, then on track 054° to DOSBE, then on track 003° to cross AAIRE at 9000 and at 210K, then on track 003° to cross JRDEN at 6000 and at 210K, then on track 003°. Expect RADAR vectors to final approach course.

LANDING RWY 23: From JONZE on track 054° to cross WHYLE between 10000 and 16000, then on track 054° to cross FREEK between 9000 and 11000 and at 250K, then on track 054° to DOSBE, then on track 021° to cross RRIKK at 9000 and at 210K, then on track 024° to cross FLAIR at 7000, then on track 056° to cross WOOOO at 7000 and at 210K, then on track 056°. Expect RADAR vectors to final approach course.

LANDING RWYS 36L/C/R: From JONZE on track 069° to cross DUBBB between 10000 and 12000, then on track 080° to cross CHELE at 7000 and at 210K, then on track 090°. Expect RADAR vectors to final approach course.

SE-2, 25 FEB 2021 to 25 MAR 2021

SE-2, 25 FEB 2021 to 25 MAR 2021